

mikejohnson

From: mikejohnson [mikejohnson@co.southampton.state.va.us]
Sent: Tuesday, October 26, 2010 4:51 PM
To: Jerry Kee
Subject: Board of Supervisors Report

Jerry,
Thanks for your report last week – I shared it with the Board Monday.

These are the concerns raised yesterday:

1. **Franklin District** – standing water in roadside ditches along Delaware Road continues to be a problem;
2. **Jerusalem District**
 - a. Vicksville Road from Rosemont to Drake – roadside ditches need to be cleaned out;
 - b. Drake Road – the dual culverts just north of Cobb Road washed out again with torrential rains of September 30 – can they be replaced with a bridge?
 - c. Rosemont Road – small section remains unpaved between Peachtree and Vicksville – can it be paved?
3. **Berlin-Ivor District** – feels like the “stepchild” since the Berlin HQ was closed – standing water a problem in roadside ditches on Seacock Chapel Road and Tucker Swamp Road
4. **Drewryville District** – still has problems on wet days with accidents in front of Valley Proteins – suspects accumulation of grease on roadway surface – VDOT previously advised that it would be resurfaced with a latex sealer with a rough finish in 2010 – can you provide a status update – 2 accidents in that location this month.

Supervisor Brown wanted me to thank you and your staff for the great response in restoring Sunbeam Road.

Michael W. Johnson
County Administrator
Southampton County
P.O. Box 400
Courtland, VA 23837
(757) 653-3015
www.southamptoncounty.org

mikejohnson

From: Kee, Jerry [Jerry.Kee@VDOT.Virginia.gov]
Sent: Friday, October 29, 2010 11:54 AM
To: Johnson, mike
Subject: FW: Board Concerns October 2010 Mtg.

Mike:

I have entered maintenance request in the work order system for our superintendents to respond. The other items should or will be addressed in the following manner:

1. **Franklin District**
Standing Water issue entered into work order system.
2. **Jerusalem District**
 - b. Drake Road – the dual pipes replacing with a bridge. We will have the hydraulics engineer review this site for possible additional improvements. Replacing with a bridge may have to be addressed with a Six Year Plan project if warranted. Also this area had approximately 11 inches of rain in 36 hours when this occurred.
 - c. Rosemont Road – This roadway must be addressed through the Six Year Plan for roadway paving.
3. **Berlin-Ivor District**
Issues entered into work order system.
4. **Drewryville District**
The area on Route 58 near Valley Protein has been scheduled in the paving plan for sealer, but will not take place until spring 2011.

Gerald W. Kee
Residency Maintenance Program Manager
Franklin Residency
Ph: (757)562-3194
Fax: (757)562-0620