

MONTHLY CONCERNS

mikejohnson

From: mikejohnson [mikejohnson@co.southampton.state.va.us]
Sent: Wednesday, December 01, 2010 10:14 AM
To: Jerry Kee
Cc: John Jenkins
Subject: Highway Issues Raised at November BOS Meeting

Jerry,
These are the issues raised at the November Board meeting. Thanks in advance for your attention and follow-up.

1. **Franklin District** – Supervisor Young raised the “same issues as last month” – water continues to stand in roadside ditches along Delaware Road. Has any work been done yet in this regard?
2. **Berlin-Ivor** – Supervisor West commented that the portion of his District served by the Capron AH was in pretty good shape, but the area served by the Franklin AH still had some outstanding issues as discussed in our face-to-face meeting on November 10. Can you provide me a brief status report on the issues raised at that meeting?
3. **Jersuaem District** – what’s the status of cleaning the roadside ditches along Vicksville Road between Rosemont and Drake?
4. **Newsoms** – Supervisor Brown advised that roadside ditches along Sunbeam Road, Riverdale Road and Sandy Ridge Road need to be reseeded. It’s my understanding that these ditches were the sources of fill material to repair the private property damage along Sunbeam Road in early October.
5. **Capron** – Supervisor Wyche questioned when Indiantown Road between Carys Bridge and Popes Station Road was scheduled for paving – there was a rumor in the community that it was scheduled for the spring of 2011. In addition, he again raised the issue of traffic westbound on Rt. 58 not being able to locate Bryant’s Church Road. Can a sign be installed along the westbound lane in advance of the crossover, “Bryants Church Road – next left.” I know the City of Suffolk has installed many of these signs along Rt. 58 – if it’s a matter of cost, we’ll be glad to pay for it.

Finally, John Jenkins asked me to forward a drainage concern to you on Beale Road in downtown Handsom. Apparently something’s plugged up that causes flooding in his and his next door neighbor’s yards with only moderate rain events. He lives at 28046 Beale Road. Can you enter it into the system and have someone respond?

Best regards,
Mike

Michael W. Johnson
County Administrator
Southampton County
P.O. Box 400
Courtland, VA 23837
(757) 653-3015
www.southamptoncounty.org

12/2/2010

November 2010 Board of Supervisors Concern

1. **Franklin District** – Ben will be contacting Supervisor Young to discuss specific locations of concern on Delaware Road. We have a ditching truck on contract now to handle spot locations.
2. **Berlin Ivor** – Final mowing is currently being completed. Culvert pipe on One Mile Road has been replaced and several others discussed are being scheduled when weather permits. Tree issues discussed near the Isle of Wight line on Route 614 have been requested through roadside for trimming. I have not received a specific schedule yet, but will update when notified. Drainage concerns near Clayton Road have been reviewed by the hydraulics engineer and we are waiting for his report and recommendations.
3. **Jerusalem District** – Discussed locations with Mr. Bryant and he will be cleaning some locations that need attentions in the next few weeks. Rosemont Road paving will have to be addressed through Secondary Six Year Plan. Drake Road culverts were questioned in October and a preliminary hydraulic review has been completed. Final study will be forwarded once additional information has been collected by the district survey group.
4. **Newsoms District** – Some of the roadside ditches that were pulled have been hydro-seeded. We reviewed and some will be reseeded shortly. The ditch material pulled was used in an approved disposal site where the damage occurred.
5. **Capron District** – Stone upgrades and drainage is being addressed at this time on Indiantown for routine maintenance. Indiantown has been moved to Rural Rustic as requested by the Board and we hope to have paved sometime this summer. We have requested information from our traffic section about the Bryants Church Road sign being installed.